

Record ID	Site Address	Septic Status	Final Inspection By	Date Final Inspection	INSPECTION WINDOW
ON0004212	18320 Main st	Final Inspection Requested	Kat McGarvy	9/19/2023	7:30-9:30AM
ON0050979	7180 Stinson	Final Inspection Requested	Harmony Graham	9/19/2023	7:30-9:30AM
ON0051594	4215 Turner Rd	Final Inspection Requested	Katie Hutchinson	9/19/2023	7:30-9:30AM
ON0050811	7830 Cowboy Rnch Vw	Open Hole Inspection	Harmony Graham	9/19/2023	9:30-11:30AM

*Per section 8.4.E.6, of the Chapter 8 regulations, all installations are expected to be 100% completed at the time request for inspection is made. Inspection windows are provided as a courtesy but please note that inspectors may inspect an installation at any time once the request is made. Should an inspector be delayed they will do their best to communicate the late arrival to the person requesting inspection; however, early arrivals will not be communicated as system completion is expected at time of request.*

**Weather Reminder: Please be advised that it is the Installers responsibility to ensure that all components are clear and accessible for inspection in the event of inclement weather. This includes the top of the tank, all effluent pipe, and the entirety of the soil treatment area. If components are not uncovered the inspection will not occur and will result in a reinspection fee upon new inspection request.**